

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:				
Company	any Rusty Netz Environmental Coordinator			
OGM	Karl Houskeeper Environmental Scientist III			

Inspection Report

Permit Number:	C0070035
Inspection Type:	COMPLETE
Inspection Date:	Thursday, December 17, 2009
Start Date/Time:	12/17/2009 12:00:00 PM
End Date/Time:	12/17/2009 4:00:00 PM
Last Inspection:	Thursday, November 12, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 25 Deg. F. InspectionID Report Number: 2226

Accepted by: jhelfric

12/28/2009

Permitee: SUNNYSIDE COGENERATION ASSOCIATES Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: SUNNYSIDE REFUSE & SLURRY

Address: ONE POWER PLANT RD, PO BOX 159 SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	310.00
Total Disturbed	202.00
Phase I	5.50
Phase II	
Phase III	

Mineral Ownership	Types of Operations
-------------------	---------------------

☐ Federal	☐ Underground
☐ State	Surface
\Box County	☐ Loadout
✓ Fee	Processing
Other	✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Date

Thursday, December 17, 2009

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Thursday, December 17, 2009

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		~	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		V	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓		✓	
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.a	a Roads: Construction, Maintenance, Surfacing	✓			
16.Ł	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	V		V	
21.	Bonding and Insurance	V		✓	
22.	Other	V			

Permit Number: C0070035 Inspection Type: COMPLETE

Inspection Date: Thursday, December 17, 2009

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The following permits were reviewed:

- -Mining permit C/007/035 issued February 3, 2008 and expires February 4, 2013.
- -UPDES permit #UT0024759 effective August 1, 2007and expires midnight July 31, 2012.
- -Air Quality Permit DAQO-702038-02 issued November 1, 2002, remains in effect.
- -SPCC plan is only applicable to plant site which is not within the permit area.
- -Certificate of Insurance effective 08/01/2009 and terminates 08/01/20010.
- -Reclamation agreement is dated December 1996 and signed by both parties.

2. Signs and Markers

The mine ID sign is located adjacent to the tipple on a light pole. The MSHA Refuse Pile sign was also checked during the inspection and contained the required information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Third quarter 2009 sediment pond inspections were done on September 17, 2009 and included in a report dated October 7, 2009. Viewed all of the sediment ponds. Several of the sediment ponds are within .5" to .6" of reaching the 60% clean elevation.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the October 2009 discharge monitoring reports.

6. Disposal of Excess Spoil, Fills, Benches

The excess disposal sites #1 & #2 were inspected on September 17, 2009 and included in the October 7, 2009 report.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected on September 17, 2009 and included in the October 7, 2009 report. The pile appeared stable. No visible hazards were observed.

20. Air Quality Permit

DAQO-702038-02 issued November 1, 2002, remains in effect. Air Quality Permit DAQE-691-99 issued August 13, 1999 was replaced by DAQO-702038-02. The permit was modified to allow the usage of a diesel generator on the power plant site. The Air Quality Permit covers both the power plant and mine site. The power plant site is not regulated by DOGM.

Permit Number: C0070035 Inspection Continuation Sheet

Inspection Type: COMPLETE

4 , , , ₁₀

Inspection Date: Thursday, December 17, 2009

Page 4 of 4

21. Bonding and Insurance

A Pledge and Escrow agreement dated January 4, 2002 is in place. The escrow agency is Wells Fargo for SCA. SCA has invested \$1,780,250.19 in federally guaranteed Treasury Notes as of December 31, 2006. The required bond amount is \$1,720,000.